

VCDS-46-Central Conv.

- Disable rear side markers in North American C7.5 S6
- Disable Entry Warning Beeps

Disable rear side markers in North American C7.5 S6

46-Central Convenience

Security Access 16017

Adaptation channels 207 & 208 for rear side markers

Document your existing numbers in case you want to re-enable later on

Change existing numbers to 0 & 32

Save

Disable Entry Warning Beeps

1. Module 46
2. Adaption, enter channel 98
3. Change 1 to 0

Part Two

1. Module 46
2. Coding, long coding helper
3. Byte 15, 00001111
4. Save exit and done
5. My byte 15 was showing 00000000 originally
6. Added the 4 1's, saved, coding accepted, power off car and restart.

<https://www.youtube.com/watch?v=Md7C2n1qQ24>