

Disable rear side markers in North American C7.5 S6

46-Central Convenience

Security Access 16017

Adaptation channels 207 & 208 for rear side markers

Document your existing numbers in case you want to re-enable later on

Change existing numbers to 0 & 32

Save

Revision #1

Created 2 March 2024 22:13:24 by Akakios

Updated 6 June 2024 03:28:55 by Akakios